



Continuing Education Course

Structural Collapse: The Hidden Dangers of Residential Fires

By James M. Dalton, Robert G. Backstrom, and Steve Kerber



To earn continuing education credits you must successfully complete the course examination.
The cost for this CE exam is \$25.00. For group rates, call (973) 251-5055

Structural Collapse:

The Hidden Dangers of Residential Fires

Educational Objectives

On completion of this course, students will:

1 Gain an understanding of the behavioral differences between solid wood joist and lightweight wood structural members under fire attack.

2 Gain an understanding of the American Society for Testing and Materials (ASTM) E119 test used to establish structural fire resistance, with modified loading conditions.

3 Gain knowledge concerning the collapse times of various floor and roof assemblies in tests recently conducted by Underwriters Laboratories (UL).

4 Gain an understanding of the benefits of ½-inch gypsum board applied to the underside of an assembly, delaying collapse.

BETWEEN 1997 AND 2008, 26 FIREFIGHTERS lost their lives in residential building collapses. The ensuing National Institute for Occupational Safety and Health (NIOSH) investigations highlighted the impact of rapid fire spread through areas of unprotected wood construction, the collapse of unprotected dimensional lumber, and the collapse of lightweight engineered wood components. In addition, departments nationwide have experienced countless near-miss incidents. Recent initiatives such as the National Fire Fighter Near-Miss Reporting System have documented more than 80 reports of incidents involving lightweight and truss construction.

In response to a growing number of line-of-duty deaths and injuries from fires involving engineered lumber, Underwriters Laboratories, Inc. (UL), in partnership with the Chicago Fire Department (CFD) and the International Association of Fire Chiefs (IAFC), was awarded funding from the Department of Homeland Security (DHS)/Federal Emergency Management Agency's (FEMA) Assistance to Firefighters Grant (AFG) program to investigate this disturbing trend and better understand the hazards firefighters face in residential buildings constructed with lightweight and wood construction.

Residential buildings are increasingly replacing conventional solid joist construction with modern lightweight construction, such as lightweight wood trusses and engineered I-joists, in roof and floor designs. These modern construction components have the same or better load-carrying capacities but don't perform as well under fire conditions mainly because there is less wood to burn. The comparison of this performance was the focus of this test series.



(1) A standing firefighter mannequin is engulfed in flames as he falls through the floor assembly behind the crawling firefighter mannequin. (Photos courtesy of authors.)

The experimental series consisted of 12 furnace fire tests of assemblies representative of typical residential “legacy” and “modern” floor and roof construction. The tests included six structural elements, three ceiling finish configurations, four floor or roof finishes, and one test examining finished ceiling penetrations (Figure 1). All of the test assemblies conformed to the dimensions and span of the available test furnace (14 feet by 17 feet). The structural members tested spanned 14 feet, even though some of the assemblies are capable of spanning greater distances because of either the material strength or joist depth of the floor or roof assembly being tested. Some the spans for these tests are conservative; view resulting failure times with this in mind. Had the structural members been allowed to support loads for a longer span, the resulting failure times would have been potentially accelerated, thus reducing the collapse time for the assembly. Measurements taken during each experiment include observation of the conditions of the ceiling and floor or roof surfaces, temperatures in the concealed space above the ceiling membrane, deflections of the floor and roof surfaces, and failure times of the tested assemblies.

This research conformed to the standard requirements of the ASTM E119, *Fire Tests of Building and Construc-*

tion Materials, testing method with one exception: the floor and roof loading requirements. The ASTM E119 testing method is normally used to certify fire resistive construction. This test series used this accepted ASTM E119 testing method to evaluate the performance of nonfire rated floor and roof construction found in legacy and modern residential construction. The current model building codes do not require fire resistance ratings for these floor and roof assemblies.

The standard set by ASTM E119 describes a fire test method that establishes a benchmark fire resistance performance between different types of building assemblies. This test relies on a standardized fire and time temperature curve, which is intended to represent a fully developed contents fire within a residential or commercial structure with temperatures reaching 1,000°F at five minutes and 1,700°F at 60 minutes. The ASTM E119 fire endurance test is designed to express fire resistance ratings in terms of hours: ½-hour, one-hour, two-hour, three-hour, and four-hour rated assemblies. These hourly time ratings are not intended to convey the actual time a specific component or assembly will withstand a real fire event. All fires are different. Variations result from room size, combustible content, and ventilation conditions. The ASTM E119 test method is designed to provide a

Figure 1. Collapse Time for Assemblies

Structural Element – Ceiling Finish	Type of Construction	Ceiling Materials	Floor/Roof Subfloor/Finish	Collapse Time (min:sec)
2 x 10 Joist Floor – Without Ceiling	Legacy	None	1 x 6 and Hardwood	18:45
2 x 10 Joist Floor – With Ceiling	Legacy	Gypsum Board	OSB and Carpet	44:45
2 x 10 Joist Floor – With Ceiling	Legacy	Lath and Plaster	1 x 6 and Hardwood	79:45
12-inch Wood I-Joist Floor – Without Ceiling	Modern Lightweight	None	OSB and Carpet	6:03
12-inch Wood I-Joist Floor – With Ceiling	Modern Lightweight	Gypsum Board	OSB and Carpet	26:45
14-inch Finger Joint Truss Floor – Without Ceiling	Modern Lightweight	None	OSB and Carpet	13:06
14-inch Finger Joint Truss Floor – With Ceiling	Modern Lightweight	Gypsum Board	OSB and Carpet	26:45
14-inch Metal Gusset Truss Floor w/ Cord Splices and Framed Stair Opening – Without Ceiling	Modern Lightweight	None	OSB and Carpet	13:20
14-inch Metal Gusset Truss Floor – With Ceiling	Modern Lightweight	Gypsum Board	OSB and Carpet	29:15
14-inch Metal Gusset Truss Floor w/ Cord Splices, Recessed Lights and Ducts With Ceiling	Modern Lightweight	Gypsum Board	OSB and Carpet	30:08
Metal Gusset Truss Roof – With Ceiling	Modern Lightweight	Gypsum Board	OSB and Shingles	13:06
2 x 6 Joist and Rafter Roof – With Ceiling	Legacy	Gypsum Board	1 x 6 and Shingles	40:00

● STRUCTURAL COLLAPSE



(2) A quadrant view of recorded video images taken during the experiments available in the Web-based outreach program.

useful benchmark for building code officials and fire protection engineers, enabling a comparison of fire performance between test samples within the laboratory environment.

Typically the ASTM E119 test procedure requires a larger, uniformly applied load to the floor designed to fully stress, or almost fail, all supporting structural members. This ultimate design load is generally higher than the uniform live load of 40 pounds per square foot (lb/ft²) prescribed by the current model building codes for residential construction. The average home with furniture arranged in a room is usually actually carrying live loads below the prescribed design live load of 40 lb/ft². To represent the average home with furniture around the perimeter of the room, a load of 40 lb/ft² was placed along two of the four sides of the floor to represent the typical conditions a firefighter encounters when entering a structure fire. To represent fire service personnel, the assemblies were also loaded with two mannequins, each



(3) Thermal imaging camera image and temperature measurement of legacy 2 x 10 joist floor—without ceiling at 1:45. Left: The thermal imaging camera view. Right: Temperature measurements above and below the finished flooring.

outfitted in fire gear and weighing 300 pounds, placed in the center of the floor or roof assembly. For the two tests that represented roof-ceiling assemblies, the two mannequins were the only live loads applied to the test assemblies.

The collapse times for all of the assemblies are shown in Figure 1. In addition to the collapse times, a large amount of significant useful data for the fire service was obtained during these fire tests, including the observation of the conditions of the ceiling and floor or roof from both sides of the assembly, temperatures in the concealed spaces, deflections of the floor and roof surfaces prior to collapse, thermal imaging camera (TIC) video from the top of the assembly, and video and audio recordings from the simulated firefighters' perspectives.


All of this information could not be included in a single article or report, so it has been developed into a Web-based outreach



program for the fire service. This free interactive program is at www.ul.com/fire/structural.html.

IMPORTANT FINDINGS

Important study findings include the following:

Floor collapse in six minutes. Engineered wood floor assemblies have the potential to collapse very quickly under well-ventilated fire conditions. When it comes to lightweight construction, there is no margin of safety. There is less wood to burn and, therefore, potentially less time to collapse. The results of tests comparing the fire performance of conventional and modern construction will improve the understanding of the hazards of lightweight construction and help incident commanders, company officers, and firefighters to evaluate the fire hazards present during a given incident and allow a more informed risk-benefit analysis when assessing life safety risks to building occupants and firefighters.






(4) Thermal imaging camera image and temperature measurement of modern lightweight 12-inch wood I-Joist floor—without ceiling at 5:30, just prior to the floor collapse. Left: The thermal imaging camera view. Right: Temperature measurements above and below the finished flooring.

The fire environment has changed. The size-up of any given structure is, for the most part, based on previous fireground experiences; most of that experience comes from fighting fires in the homes of yesterday, fairly robust 1,500-square-foot legacy-type homes constructed with solid dimensional lumber. But today, as more homes are constructed with lightweight materials, traditional size-up techniques may not provide proper risk assessment. Whether an existing renovated home or a newly constructed “McMansion,” these modern homes are the new reality. Many of today’s typical house fires are in buildings that could readily be categorized as commercial structures with commercial fuel loads. The increased size of these buildings, use of large unprotected areas of lightweight construction, and resulting fires from modern synthetic fuel loads have proven to be catastrophic. Today’s fireground operations must reflect this new reality. Adequate personnel must be dispatched and available to ensure that basic fireground operations can be completed in a safe and timely manner. Fires in today’s modern homes may require the need for additional personnel;

consider the escalation of alarms early in the operation.

Thermal imaging cameras do not provide an adequate indication of a weakened floor or pending collapse. There is a potentially dangerous misconception in the fire service that TICs can detect fire on the floor below or above a firefighter. TICs detect variations in surface temperatures for objects in the field of vision. They cannot detect temperatures if the camera is thermally shielded by the finish materials of a floor or ceiling, such as carpet or gypsum board. Average temperatures below the assembly were in excess of 1,200°F while average temperatures on top of the carpet were less than 100°F. The application of water during suppression operations will also further mask these thermal signatures in the TIC camera’s field of vision during suppression operations.

The structural performance of floor systems. Currently accepted testing standards used in the United States, such as the ASTM E119 conditions of acceptance, recognize a collapse, or structural floor failure, as one of the acceptance criteria linked to the failure time of a tested assembly. The ASTM E119 definition of collapse



A modern lightweight 12-inch wood I-joist floor—without ceiling. Collapse Time = 06:03. (5) The excessive floor deflections at the time of failure. (6) The condition of one of the surviving engineered I-joists after extinguishment.

● STRUCTURAL COLLAPSE



Modern lightweight metal gusset truss roof—with ceiling. Collapse Time = 23:15.

(7) A significant volume and velocity of smoke during initial portions of the test.

(8) The collapse of the continuous plastic ridge vent.



collapse time. If the ISO standard was applied to the unprotected engineered wooden I-joist assembly, the accepted failure time would change from 06:03 (acceptance criteria time per the ASTM E119 standard) to 04:00 (load-bearing capacity per the ISO 834:1 standard). For the fire service, this means that a complete collapse of this floor would have been seen at 06:03 but that the floor would have been severely compromised and potentially unsafe to operate on at 04:00. Be aware that although these testing methods provide documented research failure times, they also illustrate that the floors have become dangerous far before the actual documented collapse times. This trend was consistent throughout the engineered lumber assemblies tested within this study. These failures in real-life incidents may also be accelerated by larger fire loads and variations in field conditions.

Structural performance of the roof assemblies. This research also conducted two roof tests respective of finished ceiling/attic assemblies representing both “legacy” and “modern” construction. The evaluation of the structural performance

requires the floor to totally collapse within the furnace.

Several fire test standards recognized outside the United States, similar to ASTM E119, such as the International Organization for Standardization (ISO) 834:1 Fire-resistance tests—Elements of building construction—Part 1 do not rely solely on collapse as an indication of the floor’s strength. The ISO general requirements define load-bearing capacity as the elapsed time that a test sample is able to maintain its ability to support the applied load during the fire test. The ability to support the load, as defined by the standard, monitors the potential for a complete structural failure and/or when a floor is significantly weakened. This standard takes into account when a floor is progressively deflecting or failing prior to a complete structural collapse. Identifying when a floor has been significantly damaged or weakened is a critical piece of information for the fire service.

A review of the ASTM E119 and ISO 834:1 failure times as they apply to the unprotected (without ceiling) engineered wooden I-joist assembly clearly illustrates that the floor had become significantly damaged and lost its ability to carry load far before the actual total

of these assemblies and components was limited because of the available span of the furnace dimensions with respect to the overall depth of the roof structures. This is a significant limitation as the 2 × 4 metal gusset-plated roof trusses can span distances that far exceed 14 feet.

The study, however, did demonstrate a potentially dangerous and misleading ventilation phenomenon regarding installed roof vents. Initially, there was a significant amount of smoke emitting from the continuous plastic ridge vent at the beginning of the modern roof assembly test. As the temperatures increased, the continuous plastic ridge vent melted and collapsed. The collapse of the vent changed the ventilation profile for the roof. The initially heavy smoke pattern emitting from the continuous ridge vent diminished to a light indistinguishable smoke trail, although the fire was still raging below. The excessive heat created by the fire was, in effect, restricted from venting vertically through existing natural openings and created an excessively untenable condition below the roof in the attic and the occupied floor areas below the attic as the ceiling finishes failed.

Teams conducting size-up prior to fireground opera-

Modern lightweight metal gusset truss roof—with ceiling. Collapse Time = 23:15.

(9) Multiple metal gusset plate and web member failures.

(10) The deterioration of roof sheathing and ultimate failure of the roof sheathing and shingle materials.

tions may be deceived by this change in the quantity and velocity of the smoke emitting from the roof structure as they prepare to conduct fireground operations. A confined unventilated fire in an enclosed attic will accelerate the failure of roof structural elements and contribute to the failure of the ceiling materials between the attic and floors below.

Reduced smoke emitting from existing roof vents gives the wrong impression to roof teams attempting to determine if it is safe or necessary to conduct roof operations. The failure of ceiling finish materials below the attic space can also trap fire crews as fire and heat quickly overtake the floor areas below the attic level.

There is a lack of residential building code provisions regarding the average single-family residence. Building code and regulatory service groups have only recently identified the fire service as one of the potential user groups for buildings under the existing model building codes. A provision in the 2006 *International Building Code*, section 101.3, has adopted new language stating that one of the intents of the building code was to “provide safety to firefighters.” However, this code provision, which could offer a possible long-term solution, does not define to what extent the building code in any given jurisdiction adequately satisfies this requirement. Changes to model building codes often occur after a tragic loss of life. Cumulative numbers documented by NIOSH case studies alone justify the need for future changes to existing model building codes. This is especially true for one of the model building code’s most unrestrictive subgroups, the Type V-wood frame or Type III ordinary constructed residential occupancy. The fire resistive requirements for most single-family residential occupancies are minimal with regard to the exterior of the building and virtually nonexistent with regard to the interior floor and roof assemblies.

This research project demonstrated that adding a single layer of ½-inch gypsum wall board to the bottom of the unprotected floor assembly regardless of legacy or modern construction, a standard method of passive fire protection, can add on average approximately 20



minutes to the collapse time. The addition of passive fire protection requirements in the model building codes for these construction assemblies would protect not only the lives of the first responders, but would provide for the safe egress of the building occupants as well. ●

For further information on this study, please email Robert.G.Backstrom@us.ul.com, Stephen.Kerber@us.ul.com, or James.Dalton@cityofchicago.org. To submit additional information and/or photos on local fire incidents within your area that may inform the issues discussed within this article, please contact James.Dalton@cityofchicago.org.

● **JAMES M. DALTON** is the coordinator of research and development for the Chicago (IL) Fire Department.

● **ROBERT G. BACKSTROM** is a senior staff engineer with Underwriters Laboratories Inc.

● **STEVE KERBER** is a research engineer with Underwriters Laboratories Inc. and has 12 years firefighting experience.

Structural Collapse: The Hidden Dangers of Residential Fires

COURSE EXAMINATION INFORMATION

To receive credit and your certificate of completion for participation in this educational activity, you must complete the program post examination and receive a score of 70% or better. You have the following options for completion.

Option One: Online Completion

Use this page to review the questions and mark your answers. Return to www.FireEngineeringUniversity.com and sign in. If you have not previously purchased the program, select it from the "Online Courses" listing and complete the online purchase process. Once purchased, the program will be added to your **User History** page where a **Take Exam** link will be provided. Click on the "Take Exam" link, complete all the program questions, and Submit your answers. An immediate grade report will be provided and on receiving a passing grade your "Certificate of Completion" will be provided immediately for viewing and/or printing. Certificates may be viewed and/or printed anytime in the future by returning to the site and signing in.

Option Two: Traditional Completion

You may fax or mail your answers with payment to *PennWell* (see Traditional Completion Information on following page). All information requested must be provided to process the program for certification and credit. Be sure to complete ALL "Payment," "Personal Certification Information," "Answers," and "Evaluation" forms. Your exam will be graded within 72 hours of receipt. On successful completion of the post test (70% or higher), a "Certificate of Completion" will be mailed to the address provided.

COURSE EXAMINATION

- Between 1997 and 2008, 26 firefighters loss their lives in residential building collapses. These collapses can be contributed to the impact of one or a combination of which of the following circumstances?
 - The impact of rapid fire spread through areas of unprotected wood construction.
 - The collapse of unprotected dimensional lumber.
 - The collapse of engineered wood components.
 - All of the above.
- What was the focus of the research conducted by Underwriters Laboratories, the Chicago Fire Department, and the International Association of Fire Chiefs funded by the Department of Homeland Security/Federal Emergency Management Agency's Assistance to Firefighters Grant Program?
 - To better understand the hazards firefighters face in residential buildings constructed with lightweight and wood construction.
 - To compare the performance of typical residential legacy construction to modern construction for floor and roof assemblies.
 - To evaluate the passive fire protection contributions provided by various standard ceilings finish materials.
 - All of the above.
- ASTM E119, *Fire Tests of Building and Construction Materials*, relies on a standardized fire and time temperature curve, which is intended to represent a fully developed contents fire within a residential or commercial structure. What is the temperature for this test at five minutes?
 - 500°F
 - 750°F
 - 1,000°F
 - 1,250°F
- The ASTM E119, *Fire Tests of Building and Construction Materials*, fire endurance tests are designed to express fire resistance ratings in terms of hours: ½-hour, one-hour, two-hour, three-hour, and four-hour rated assemblies. What are these hourly ratings intended to convey?
 - The actual time a specific component or assembly will withstand a real fire event.
 - The time the fire department has to operate in a structure fire.
 - A useful benchmark for building code officials and fire protection engineers to compare the fire performance of test samples within a laboratory environment.
 - Time until the floor assembly deflects two inches.
- The ASTM E119 fire endurance test is conducted on a test furnace (14 ft. by 17 ft.). For the DHS/AFG-sponsored test series, the structural members spanned 14 feet, even though some of the assemblies were capable of spanning greater distances. As some of the spans for these tests were conservative, what does this mean for the resulting failure times?
 - Had the structural members been allowed to support loads over a longer span, the resulting failure times would have been potentially accelerated.
 - Had the structural members been allowed to support loads over a longer span, the resulting failure times would have been potentially decelerated.
 - There would be no impact if the spans were longer.
 - None of the above.
- The DHS/AFG-sponsored test series conformed to the standard requirements for the ASTM E119, *Fire Tests of Building Construction Materials*, testing method with one exception. What was that exception?
 - The floor- and roof-loading requirements.
 - The prescribed ASTM E119 time temperature curve.
 - The span of the members.
 - The ventilation conditions.
- Thermal imaging cameras (TICs) do not provide an adequate indication of a weakened floor or pending structural collapse. TICs detect variations in surface temperatures for objects in the field of vision. They cannot detect temperatures if the camera is thermally shielded by finish materials. What were the average temperatures below the assembly and on top of the finish flooring materials documented in the DHS/AFG-sponsored test series?
 - There was no recorded difference.
 - The average temperature below the assembly was in excess of 1,200°F while average temperatures on top of the carpet were less than 100°F.
 - The average temperature below the assembly was in excess of 600°F while average temperatures on top of the carpet were less than 100°F.
 - The average temperature below the assembly was in excess of 1,200°F while average temperatures on top of the carpet were 600°F.

Structural Collapse: The Hidden Dangers of Residential Fires

8. Typically the ASTM E119 test procedure requires that the assemblies be subjected to an applied uniform load to fully stress, or almost fail, all supporting structural members. The DHS/AFG-sponsored test series subjected only partial floor areas to the uniform live load prescribed by current model building codes for residential construction. What is this prescribed live load required by the model building codes?
- 30 lb/ft²
 - There is no live load requirement
 - 40 lb/ft²
 - 100 lb/ft²
9. For the DHS/AFG test of the unprotected (without ceiling) engineered wooden I-joint, what was the accepted failure time per the ASTM E119 standard, or the time of complete collapse, for this tested assembly?
- 04:00
 - 05:00
 - 06:03
 - 07:03
10. In terms of an assembly's structural performance, what condition of acceptance does ISO 834:1 *Fire Resistance Tests—Elements of Building Construction—Part 1* (used outside of the United States) use to document the failure time of a tested assembly?
- Collapse or structural failure only.
 - The ability to support load, accounting for a complete structural failure and/or when a floor may have become significantly weakened.
 - Breach of assembly by smoke and fire.
 - The ability for firefighters to stand on the assembly.
11. For the DHS/AFG test of the unprotected (without ceiling) engineered wooden I-joint, what was the load-bearing capacity per the ISO 834:1 standard, or the time that the floor would have been severely comprised and potentially unsafe to operate on, for this tested assembly?
- 04:00
 - 05:00
 - 06:03
 - 07:03
12. Of the five types of building construction, which subgroups are the most unrestrictive in terms of fire resistance requirements?
- I
 - III
 - V
 - Both B and C are correct
13. The DHS/AFG-sponsored test series demonstrated that adding a single layer of ½-inch gypsum wall board to the bottom of the unprotected floor assembly, regardless of legacy or modern construction, can add on average approximately how many minutes to the collapse time of the tested assembly?
- 15 minutes
 - 20 minutes
 - 30 minutes
 - 60 minutes
14. The fire environment has changed. Many of today's house fires are in buildings that could readily be categorized as commercial structures with commercial fuel loads. Why is this the case?
- The increased size of the buildings.
 - The use of large unprotected areas of lightweight construction.
 - The resulting fires from fuel loads from modern synthetic materials.
 - All of the above.
15. There is a potentially dangerous misconception in the fire service that TICs can detect fire on the floor below or above a firefighter. What do TICs do?
- TICs can provide an adequate indication of a weakened floor.
 - TICs can provide an adequate indication of a pending structural collapse.
 - TICs can detect fire on the floor below or above a firefighter.
 - TICs detect variations in surface temperatures for objects in the field of vision.
16. What common fireground operation will mask the thermal signatures in the TIC's field of vision during suppression operations?
- Vertical ventilation.
 - The application of water.
 - Horizontal ventilation.
 - Salvage operations.
17. The DHS/AFG-sponsored research did observe a potentially dangerous and misleading ventilation phenomenon while testing the modern constructed roof assembly relating to what component of the roof assembly?
- Metal gusset plate connections.
 - Oriented strand board (OSB) roof sheathing.
 - Continuous ridge vents.
 - Continuous eaves and soffits.
18. What building material was associated with the potentially dangerous ventilation phenomenon noted in the modern constructed roof assembly?
- Galvanized steel
 - Plastic
 - Wood
 - Concrete
19. What are the potential effects associated with a confined unventilated fire in an enclosed attic area?
- An accelerated failure of roof structural elements.
 - Contribution to the failure of the ceiling materials between the attic and floors below.
 - A decelerated failure of roof structural elements.
 - Both A and B are correct.
20. What potential fireground hazards does a confined unventilated fire in an enclosed attic area present to operating personnel?
- Reduced smoke emitting from existing roof vents gives the wrong impression to roof teams attempting to determine if it is safe or necessary to conduct roof operations.
 - Teams conducting size-up prior to fireground operations may not be deceived by changes in the quality and velocity of smoke emitting from the roof structure as they prepare to conduct fireground operations.
 - The failure of ceiling finish materials below the attic space can also trap fire crews as fire and heat quickly overtake the floor areas below the attic level.
 - Both A and C are correct.

Structural Collapse: The Hidden Dangers of Residential Fires

PROGRAM COMPLETION INFORMATION

If you wish to purchase and complete this activity traditionally (mail or fax) rather than Online, you must provide the information requested below. Please be sure to select your answers carefully and complete the evaluation information. To receive credit, you must answer at least six of the eight questions correctly.

Complete online at: www.FireEngineeringUniversity.com

PERSONAL CERTIFICATION INFORMATION:

Last Name (PLEASE PRINT CLEARLY OR TYPE)

First Name

Profession/Credentials License Number

Street Address

Suite or Apartment Number

City/State Zip Code

Daytime Telephone Number with Area Code

Fax Number with Area Code

E-mail Address

TRADITIONAL COMPLETION INFORMATION:

Mail or fax completed answer sheet to
Fire Engineering University, Attn: Carroll Hull,
1421 S. Sheridan Road, Tulsa OK 74112
Fax: (918) 831-9804

PAYMENT & CREDIT INFORMATION

Examination Fee: \$25.00 Credit Hours: 4

Should you have additional questions, please contact Pete Prochilo (973) 251-5053 (Mon-Fri 9:00 am-5:00 pm EST).

- I have enclosed a check or money order.
- I am using a credit card.

My Credit Card information is provided below.

- American Express Visa MC Discover

Please provide the following (please print clearly):

Exact Name on Credit Card

Credit Card # Expiration Date

Signature

ANSWER FORM

Please check the correct box for each question below.

- | | |
|---|---|
| 1. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D | 11. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D |
| 2. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D | 12. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D |
| 3. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D | 13. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D |
| 4. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D | 14. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D |
| 5. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D | 15. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D |
| 6. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D | 16. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D |
| 7. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D | 17. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D |
| 8. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D | 18. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D |
| 9. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D | 19. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D |
| 10. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D | 20. <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D |

COURSE EVALUATION

Please evaluate this course by responding to the following statements, using a scale of Excellent = 5 to Poor = 1.

- | | | | | | |
|--|-------|---|---|-----|----|
| 1. To what extent were the course objectives accomplished overall? | 5 | 4 | 3 | 2 | 1 |
| 2. Please rate your personal mastery of the course objectives. | 5 | 4 | 3 | 2 | 1 |
| 3. How would you rate the objectives and educational methods? | 5 | 4 | 3 | 2 | 1 |
| 4. How do you rate the author's grasp of the topic? | 5 | 4 | 3 | 2 | 1 |
| 5. Please rate the instructor's effectiveness. | 5 | 4 | 3 | 2 | 1 |
| 6. Was the overall administration of the course effective? | 5 | 4 | 3 | 2 | 1 |
| 7. Do you feel that the references were adequate? | | | | Yes | No |
| 8. Would you participate in a similar program on a different topic? | | | | Yes | No |
| 9. If any of the continuing education questions were unclear or ambiguous, please list them. | _____ | | | | |
| 10. Was there any subject matter you found confusing? Please describe. | _____ | | | | |
| 11. What additional continuing education topics would you like to see? | _____ | | | | |

PLEASE PHOTOCOPY ANSWER SHEET FOR ADDITIONAL PARTICIPANTS.

AUTHOR DISCLAIMER
The author(s) of this course has/have no commercial ties with the sponsors or the providers of the unrestricted educational grant for this course.

SPONSOR/PROVIDER
No manufacturer or third party has had any input into the development of course content. All content has been derived from references listed, and/or the opinions of the instructors. Please direct all questions pertaining to PennWell or the administration of this course to Pete Prochilo, peter@penwell.com.

COURSE EVALUATION and PARTICIPANT FEEDBACK
We encourage participant feedback pertaining to all courses. Please be sure to complete the survey included with the course. Please e-mail all questions to: Pete.Prochilo@penwell.com.

INSTRUCTIONS
All questions should have only one answer. Grading of this examination is done manually. Participants will receive confirmation of passing by receipt of a verification form.

EDUCATIONAL DISCLAIMER
The opinions of efficacy or perceived value of any products or companies mentioned in this course and expressed herein are those of the author(s) of the course and do not necessarily reflect those of PennWell.

Completing a single continuing education course does not provide enough information to give the participant the feeling that s/he is an expert in the field related to the course topic. It is a combination of many educational courses and clinical experience that allows the participant to develop skills and expertise.

COURSE CREDITS/COST
All participants scoring at least 70% on the examination will receive a verification form verifying 4 CE credits. Participants are urged to contact their state or local authority for continuing education requirements.

RECORD KEEPING
PennWell maintains records of your successful completion of any exam. Please go to www.FireEngineeringUniversity.com to see your continuing education credits report.

© 2009 by Fire Engineering University, a division of PennWell.